Approved For Delease 20029F0F25PCMARDPF4B004966

	2912		
--	------	--	--

FILE IN 9 MAY 110 840		When Filled In) REPRODUCTION PROHIBITED		27 MAY / 1 08 20	
	2	7	12	17	
	3	8	13	18	
	4	9	14	19	
	5	10	15	20	

NNNS E CRET 270559Z MAY 71 CITE

25X1A 25X1A

25X1A

IMMEDIATE

SUBJ: MISSION C-151C

LONG SHAFT SYST MALFUNCTION CAUSE HAS BEEN RESOLVED AND MISSION GENERATION IS PROCEEDING. DEFICIENCY DISCOVERED IN K-5 RELAY IN L/S A-3 RECEIVER ASSEMBLY. PROBLEM WAS DUPLICATED ON BENCH CHECK.

FYI TROUBLE INDICATION WAS LOSS OF LOG VIDEO AT Ø344Z (MISSION C-141C).

G P-1

SECRET

BT

